



Photo 1 – Engine at Recovery Facility



Photo 2 – Spark Plug Tray



Photo 3 – Close Up - #1 Bottom (Courtesy Rotech)



Photo 4 – Close Up, #2 Bottom (Courtesy Rotech)



Photo 5 – Close Up, #3 Top (Courtesy Rotech)



Photo 6 – Close Up, #3 Bottom (Courtesy Rotech)